

# [Repair of a denture broken at the clasp]

Components to be used



Super-Bond C&B



Opaque Pink



META FAST  
Powder      Liquid



1 Sand-blasting with alumina



2 Dispensing

Opaque Pink




3 Brush-dip technique



4 Applying and curing



5 Building up with the resin



6 Curing



7 Finishing